



THESE TWO CAPS ARE NOT ROUTED CORRECTLY. NEED TO RE ROUTE TO CONNECT DIRECTLY TO CHIP POWER PINS. ADD CAPS ON PINS OF CHIPS U1 AND U2 TEMPORARILY.